#### Real Property Records

Date last updated: Friday, March 05, 2004



#### **3** Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

Link to property tax information for this property
Link to property sales information for this neighborhood
Link to property sales information for all Denver neighborhoods

#### PROPERTY INFORMATION

Property Type: Residential

Name and Address Information

CARLSON, JEFFREU D

2835 S MONACO PKWY #1303

**DENVER, CO 80222** 

3843 GILPIN ST

Property Address:

Parcel: 0223406020000

Legal Description

Tax District

L 27 & S 3FT OF L 28 BLK 9

PROVIDENT PARK

RESIDENTIAL

DENV

Assessment Information

Actual	Assessed	Exempt	Taxable
19300	1540		
112900	8990		
132200	10530	0	10530
	•		
11600	1060		
93400	8550		
105000	9610	0	9610
	19300 112900 132200 11600 93400	19300 1540 112900 8990 132200 10530	19300 1540 112900 8990 132200 10530 0 

Style: One Story

Year Built: 1891

Building Sqr. Foot: 814

Bedrooms: 1

Dedicoms. 1

Baths Full/Half: 1/0

Basement/Finished: 0/0

Lot Size: 3,500

Zoning: R2


Reception No.: 0000205522

Recording Date: 09/30/03

Document Type: Warranty

Sale Price: 97500

Mill Levy: 64.162



1) 2305 -001- DWC	13:10 Hours	06-16-06
2) 2365 - 002 - DWC	13:20 Hours	06-16-06
3) 2305 -001- SCC	13:35 Hours	06-16-06 / offer
4) 2305 - 002 - 566	13:45 Hours =	06-16-06 / offset
5)		
6)		



4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 2305-001-DWC Client Project ID: 213001.01 Date Collected: 6/16/06 Date Received: 6/20/06

Method: SW6010

Lead

Lab Work Order: 06-3902 Lab Sample ID: 06-3902-13 Sample Matrix: Wipe

5.3

**METALS** 

Prep Method: SW6010

062206PM **Dilution Factor:** Date Prepared: 6/21/06 Lab File ID: Date Analyzed: 6/23/06 Method Blank: MB-10200 Lab Fraction ID: 06-3902-13A

7439-92-1

**CAS Number** Result Analytes LQL Units

μg/WIPE

Approved

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if

compound is undetected, LQL exceeds MCL.

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

4.0

Surr - Surrogate

Print Date: 6/23/06

### Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 2305-002-DWC Client Project ID: 213001.01 6/16/06 Date Collected: Date Received: 6/20/06

Lab Work Order: 06-3902 Lab Sample ID: 06-3902-14 Sample Matrix: Wipe

**METALS** 

Method: SW6010

Prep Method: SW6010

Date Prepared: 6/21/06 Date Analyzed: 6/23/06

**Analytes** 

Lab File ID: 062206PM

Dilution Factor:

Method Blank: MB-10200 Lab Fraction ID: 06-3902-14A Result **CAS Number** LQL Units

48 7439-92-1 4.0 μg/WIPE Lead

Definitions: NA - Not Applicable

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Approved

LQL - Lower Quantitation Limit

Surr - Surrogate

### Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 2305-001-SCC Client Project ID: 213001.01 Date Collected: 6/16/06 Date Received: 6/20/06

Lab Work Order: 06-3902 Lab Sample ID:

06-3902-15

Sample Matrix:

Soil

**METALS** 

Prep Method: SW3050 Method: SW6010

Date Prepared: 6/21/06 Lab File ID: 062206PM **Dilution Factor:** 

Date Analyzed: 6/22/06 Method Blank: MB-10205 Lab Fraction ID: 06-3902-15A

**Analytes CAS Number** Result LQL 7439-92-1 33 Lead 5.9 mg/Kg

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if

compound is undetected, LQL exceeds MCL.

Approved

**Definitions:** NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 6/23/06

### Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 2305-002-SCC Client Project ID: 213001.01 Date Collected: 6/16/06 Date Received: 6/20/06

Lab Work Order: 06-3902 Lab Sample ID: 06-3902-16

Sample Matrix: Soil

**METALS** 

Prep Method: SW3050 Method: SW6010

Date Prepared: 6/21/06 Lab File ID: 062206PM **Dilution Factor:** 

Date Analyzed: 6/22/06 Method Blank: MB-10205 Lab Fraction ID: 06-3902-16A

**CAS Number** Result **Analytes** LQL Units 7439-92-1 38 5.5 Lead mg/Kg

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.


Approved

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 6/23/06



North South East West

Metal Inm/Gutters/Downspouts			M	ISC STUCTURE	s/Garage/Fen	ces	
Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)
	<del></del>	<u> </u>					
		ļ				ļ	
		<del> </del>				ļ <u>.</u>	
		ì	1 1			1	

Site	Results	PbC	Floor	Room	Component	Substrate	Side	Condition	Color	
2305	Positive	26.5	FIRST	PORCH	COLUMN	WOOD	EAST	CRACKED	BROWN	0k
2305	Negative	0.17	FIRST	PORCH	EXT WALL	PLASTER	NORTH	CRACKED	BROWN	
2305	Negative	0.01	FIRST	OUTSIDE	EXT WALL	BRICK	NORTH	CRACKED	BROWN	7
£305	Positive	6.7	FIRST	OUTSIDE	EXT WALL	CONCRETE	EAST	Ç (₫D	BROWN	一、.
१ु95_	Positive	16.9	FIRST	OUTSIDE	WINDOW FRAME	WOOD	SOUTH	CRACKED	BROWN	
305	Positive	8.2	FIRST	PORCH	SIDING	WOOD	SOUTHING	CRACKED	BROWN	- P
2305	Negative	0.05	FIRST	OUTSIDE	FOUNDATION	PLASTER	WEST TO	CRACKED	BROWN	
2305	Negative	0.04	FIRST	PORCH	ROOF TRIM	WOOD	WEST	CRACKED	BROWN	一,,
2305	Positive	9.9	SECOND	PORCH	ROOF TRIM	WOOD	EAST	PEELING	- BROWN	W ->
			i <del> </del>							
						<u> </u>				
			<u> </u>					·		
						•				
Vote:	Readings are in n	ng/cm²	1							
			<u> </u>	_i						
Painte	d surfaces not tes	ted were asses	ssed to be in	'intact' conditior	n at time of site visit.					

Ok to do entire Front porch including colum up to exphellon porch.

To Not do entire beek porch (engling wood) a bote appear baked, but is not into both it.

So Not do any on set time anywhere.

The Not do any on set time

# Color Photo(s)

The following pages contain color that does not appear in the scanned images.

To view the actual images, contact the Region VIII Records Center at (303) 312-6473.

## Property ID # 2305 / 3843 Gilpin Street



East exposure of house



Wood trim above porch contains peeling lead paint



Wood porch columns & trim contain peeling lead paint

Property # 2305: Wood siding on northeast corner of house contains peeling lead paint




Northeast corner of house




East exposure of wood siding on house

This spreadsheet performs screening level calculations to estimate the effect of peeling leaded paint on the average concentration of lead in yard soil 3843 Gilpin St.

INPUTS	Variable	Units	House
General	Mixing depth in yard	cm	2.54
	Mixing depth in yard	inches	1
	Soil density	g/cm3	2.5
	RBC in soil	mg/kg	400
	Bkg in clean fill	mg/kg	50
			Small
House-specific	Area of the exposure unit	m2	72.46437
	Area of the exposure unit	ft2	780
	Concentration of lead in paint	mg/cm2	26.5
	Area of peeling paint	m2	19.69544
	Area of peeling paint	ft2	212
COMPUTATIONS	:		
COMI CIATION	Mass of lead from paint	mg	5.2E+06
	Volume of soil	cm3	1.8E+06
	Mass of soil	kg	4.6E+03
	Incremental concentration	mg/kg	1134.3
	Maximum acceptable area of p		6.1
	Maximum acceptable area of p	. , ,	65.4
DECISION			Not OK





North South East West

Exterior Walls - BLOWN					Doc	orstrim	
Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)
BRICK		CRACK					
W000 SIDING		CRACK	8,2				
CEMENT				WOOD	170'1	PEEL	-9,9
				WOOD		PEEL	

North South East West

Window Trim/Pascia/Soffit - BROWN				Patios/D	ecks/Porches	-BROWN	
Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)
				CEMENT WALL		CRACK	
WOOD		CRACK	16.9				
CEMBNISILL			617	MOOD COLVAN	42'F	CRACK	26.5
				I			

North South East West

Metal Trim/Gutters/Downspouts			M	isc Structure	s/Garage/Fen	ces	
Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)
	· · · · · · · · · · · · · · · · · · ·						
1			1	1			ľ

Site	Results	PbC	Floor	Room	Component	Substrate	Side	Condition	Color
2305	Positive	26.5	FIRST	PORCH	COLUMN	WOOD	EAST	CRACKED	BROWN
2305	Negative	0.17	FIRST	PORCH	EXT WALL	PLASTER	NORTH	CRACKED	BROWN
2305	Negative	0.01	FIRST	OUTSIDE	EXT WALL	BRICK	NORTH	CRACKED	BROWN
2305	Positive	6.7	FIRST	OUTSIDE	EXT WALL	CONCRETE	EAST	CRACKED	BROWN
2305	Positive	16.9	FIRST	OUTSIDE	WINDOW FRAME	WOOD	SOUTH	CRACKED	BROWN
2305	Positive	8.2	FIRST	PORCH	SIDING	WOOD	SOUTH	CRACKED	BROWN
2305	Negative	0.05	FIRST	OUTSIDE	FOUNDATION	PLASTER	WEST	CRACKED	BROWN
2305	Negative	0.04	FIRST	PORCH	ROOF TRIM	WOOD	WEST	CRACKED	BROWN
2305	Positive	9.9	SECOND	PORCH	ROOF TRIM	WOOD	EAST	PEELING	BROWN
Note: 1	Readings are in n	ng/cm <sup>2.</sup>							
		<del>-</del>		_		<del> </del>			
Painted	surfaces not tes	ted were asses	sed to be in	'intact' condition	at time of site visit.				

## Property ID # 2305 / 3843 Gilpin Street



East exposure of house



Wood trim above porch contains peeling lead paint



Wood porch columns & trim contain peeling lead paint

Property # 2305: Wood siding on northeast corner of house contains peeling lead paint



Northeast corner of house



East exposure of wood siding on house

2305

Х

<> Ing New Update Test Cancel Exit Ficker # 0000203881-000 has been quened! 04 20 04 04 03 26 PM NEW INSERT

Ticket 0000203881 Date 04/20/2004 Time 04:02PM Oper **JWL381808610** Rev 000 NEW GRID old Tkt 0000203881 Date 04/20/2004 Time 04:02PM Oper **JWL381808610** Chan WEB

Phone 303-487-0377 Ext

Caller JASON LYNCH

Email JLYNCH@PROJECTRESOURCESING.COM

Company PROJECT RESOURCES

Fax 303-295-0990

Address 10 E 55TH AVE

City DENVER

State co Zip 80216

Alternate Contact TODD MYERS

Phone 3034870377

Ext

Done for corps of engineers / EPA

Work type SOIL EXCAVATION TO A DEPTH OF 12 INCHES F

Explosives N Boring N

Meet time requested N

St co Cnty DENVER

Place **DENVER** 

Addr From 3843

Street GILPIN STREET

Nearest Intersecting Street

Latitude Longitude

Location ENTIRE RESIDENTIAL PROPERTY FROM THE CURB UP ONTO THE PROPERTY AT THE ADDRESS LISTED - SOIL EXCAVATION TO A DEPTH OF 12 INCHES.

The locate will be completed between 04/20/04 04:03:20 PM and the end of the day 04/22/2004

Grids (T/R/S) 038068W23SE

360NT1 ADSTA1 CMSDC00 CMSND14 ICGTL3 LVL311 MC101 PCKVEL PCND00 PSND14 QLNCND00 QLNCND14 SPRN01 SPRNTA TACO01 TCHAM1 TCHAM2 TWTEL1 WCG01

Members - these will be notified by the center

ICGTL3

ICG TELECOMMUNICATIONS AKA INTELCOM

ICG TELECOMMUNICATIONS

PCND00


XCEL ENERGY

XCEL ENERGY

	XCEL ENERGYAPPT FILE	XCEL ENGYAPPT SCHEDULE UQ
PCKVEL	XCEL ENERGYELEC TRANSM	XCEL ENERGY-ELEC TRANSM
CMSDC00	COMCAST-CATV	COMCAST-CATV/UQ
PCKVEL		
PSND14	XCEL ENERGYAPPT FILE	XCEL ENGYAPPT SCHEDULE UQ
QLNCND14	QWEST LOCAL NETWORKAPPT. SCHED.	QWEST LOCAL NETWORK
QLNCND14	QWEST LOCAL NETWORKAPPT. SCHED.	QWEST LOCAL NETWORK
LVL311	LEVEL 3 COMMUNICATIONS	LEVEL 3 COMMUNICATIONS
MCI01	MCI	MCI
PCKVEL	XCEL ENERGYELEC TRANSM	XCEL ENERGY-ELEC TRANSM
WCG01		
QLNCND00	QWEST LOCAL NETWORK	QWEST LOCAL NETWORK (UQ)
TCHAM2	TOUCH AMERICASOUTHERN COLORADO AREA	TOUCH AMERICA (FIBER)
ADSTA1	ADESTA COMMUNICATIONS	ADESTA COMM
360NT1	360NETWORKS, INC.	360NETWORKS, INC FIBER
QLNCND00	QWEST LOCAL NETWORK	QWEST LOCAL NETWORK (UQ)
CMSND14		COMCAST-CATV/UQ
ICGTL3	icg telecommunications AKA intelcom	ICG TELECOMMUNICATIONS
PSND14	XCEL ENERGYAPPT FILE	XCEL ENGYAPPT SCHEDULE UQ
PCND00	XCEL ENERGY	XCEL ENERGY
CMSDC00		COMCAST-CATV/UQ
CMSND14	COMCAST-APPT. SCHED.	COMCAST-CATV/UQ
TCHAM1	TOUCH AMERICA	TOUCH AMERICA (FIBER)
SPRNTA	TOUCH AMERICACOPY TERMINAL TO SPRINT	TOUCH AMERICA-COPY TERM
TWTEL1	TIME WARNER TELECOM	TIME WARNER TELECOM
TACO01	TOUCH AMERICA - COLORADO	TOUCH AMERICA-COLORADO
PCND00	XCEL ENERGY	XCEL ENERGY
SPRN01	U.S. SPRINT	U.S. SPRINT

#### TIER2 MEMBERS - you must notify these members yourself

DTEO01	DENVER TRAFFIC ENGINEERING OPERATIONS	DNVR TRAFFIC ENG OPERAT.	720-865-4001
DNVH20	DENVER WATER DEPARTMENT	DENVER WATER DEPT	303-628-6666
WWMG01	WASTEWATER MANAGEMENT DIVISION	WASTEWATER MGMT DIVISION	303-446-3744



### **Consent For Access To Property**

#### RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name:	Phone: 363 - 756-6	<u>-</u>
Jeffrey Carlson		,54
<u> </u>		
	Address: 3843 Gilpin St	
Addresses of	Address:	
Properties covered by	Address:	
this Agreement:	Address:	
	Address:	

#### PURPOSE OF RESPONSE ACTIVITIES

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed, the Grantor will have an opportunity to review and approve the planned soil removal, and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

#### ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:

2305

### Consento para el Acesso de la Propiedad

#### DERECHO A ENTRAR LA PROPIEDAD

Otorgante (dueño(a) de propiedad) se da consento y autoriza la Agencia para la Proteccion del Medio Ambiente de Los Estado Unidos (EPA) o su representantes autorizado, en conjunto el Cesionario, a entrar y llevar a cabo algunas actividades ambientales acerca de la propiedad describido que sigue:

Dueño de la Propiedad	•	Numero Diario:
Jeffrey Carlson		
<b></b>		
	Dirección: 3843 Gil	pin St
Dirección de Propiedades Cubieto por este Acuerdo:	Dirección:	
	Dirección:	
	Dirección:	
	Dirección:	

#### PROPÓSITO DE ACTIVIDADES AMBIENTALES

El EPA solicita el acesso a collectar muestras de tierra y remover tierra que tiene alta concentraciónes de arsénico y/o plomo que podría ser peligroso a su salud. La tierra estará removido y el(los) area(s) excavado(s) estará reemplazado con materials limpias y restaurado. Este trabaja estará realizado abajo del Vasquez Boulevard/I-70 Superfund Site programa de remediación.

Un representante de EPA se contactará el Otorgante pesonalmente a discutir el trabajo estar realizado, el Otorgante tendrá la oportunidad a examinar y sancionar el plan de removimiento de tierra y el trabajo de restoración antes de comenzar. Cuando el trabajo se termina, el Otorgante estará pedido a revisar el trabajo, confirmar su terminación y cumplir con su aprobación. Después de terminación, el Otorgante recibirá un documento escrito por el EPA que indica la propiedad había sido remediado.

#### ACCIONES DE LA RESPONDENCIA AMBIENTAL.

Por su firma de este Acuerdo de Acceso, el Otorgante concede el EPA, sus empleos, contractors y subcontractors el derecho a entrar la propiedad, en tiempos razonable y sin noticia anterior, para el unico propósito a realizar trabajo. Este acceso debería persistir en efecto hasta que el trabajo había sido terminado en un estado aceptado. El Ortogante tamiben está de acuerdo con:

- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc;
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

#### AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact Jennifer Chergo at 303-312-6601 or Pat Courtney at 303-312-6631.

I grant access to m	y properties	☐ I do not grant acc	ess to my properties
Signature 303-756-65	<u> </u>	Signature	Date
☐ I would like to be	present during any samp	oling that is required.	

- Remover obstruciónes que incluye botes, remolque, vehículos, jugetes de niños, montones de madera, casas de perros, etc.
- Remover de bulbos de flores, o otras plantas que el Otorgante o inquilino del Otorgante quisiera guardar;
- Regar y mantener reemplazo de vegetación, incluso la aplicación de fertilizante, como es necesario subsecuente de la riega inicial por el EPA, a menos que regando está restringido por la Junta de Agua de Denver.
- Permanecer por la guia de Salud y Seguridad proveido por el EPA;
- Si la propiedad está rentado, asiste el EPA a obtener la aprobación del inquilino para acceso a la propiedad a llevar a cabo el trabajo, si el EPA está inhábil a obtener acceso; y
- Permitir a hacer un video y/o tomar fotos de la propiedad incluyendo los areas exterior y interior de edificios.

#### ACUERDO A NO INTERFERIR

El Otorgante está de acuerdo a no interferir o meterse en cualquier actividades o trabajo hecho, o el equipo usado a llevar de cabo los actividades, o hacer cualquier acciones en respecto de la usa de dicho propiedad que podría arriesgar la salud o bienestar de los Cesionarios o el medio ambiente, o permitir otras personas a usar la propiedad en alguna manera.

Si tiene preguntas sobre este programa, por favor contacta Jennifer Chergo at 303-312-6601 or Pat Courtney at 303-312-6631.

Si yo permito acceso a mi propiedad		No permito acceso a mi propiedad.		
Firma	Fecha	Firma	Fecha	
☐ Me gustaría sei	r presento durante de cualqu	ier colleción de muestras.		



### **Property Completion Agreement**

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

Property ID: 2305		
Property Address: 3843 Gilpin	\$	
Owner: Jethrey Carloon		
Phone: 303-4756-6502		
Restoration Items in Question:		
Item:		
Item:		
Item:		
Item;	·	
Item:		
Item:		
Additional Comments:		
•		,
		<u>, , , , , , , , , , , , , , , , , , , </u>
I agree restoration is completed, except as noted		
I do not agree restoration is completed .		
I agree that the sprinkler system is working properly following reinstallation by contractor		
Jan 6-11-04	( faring	6/1110
Owner's Signature Date	Contractor's Signature	Date

## **Property Access Checklist**

Property ID: 2305			( STARTED ON:/_/_
Property Address: 3843 Silpin		☐ WORE	K COMPELTED ON://_
Property Owner: Jeffcey Can	-150n	Property R	
Mailing Address:		Home Phon	16:
	-	Fax:	
Home Phone: 30.7 - Classic 1.50.7		Cell/Pager:	Information:
Fax: 303-750-650	,2		n aprox - training, com
Cell/Pager:	···	Jeguso	K B C C C C C C C C C C C C C C C C C C
,			
Notification Letter	Sent:/	,	By: Any JAMS
Access Agreement	Signed:		
Restoration Agreement	Signed:		By: Jeff Parlson  By: Jeff Carlson
Topsoil Sampling (if applicable)			By:
Disposal Sampling (if applicable)			By:
Garden Sampling (if applicable)			By:
Utility Clearance	Called://		By:
Video/Photos (Before)	On://		By: Keith rodd
☐ Video/Photos (During)	On://		By:
☐ Video/Photos (After)	On://		By:
☐ Video/Photos (30-Day)	On://		By:
Property Completion Agreement	Signed://		By:
☐ Final Report	Issued://		By:
	L		
Air Monitoring (as applicable)	. ,		
Community Crew On:	<u>.//</u>	By:	
'			
		By:	
Results:			
☐ Community ☐ Crew On:	//_	By:	
Results:	<del></del>	<del> </del>	
	<u></u> .		

### **Restoration Agreement**

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: 2305	
Property Address: 3 % (13	
Owner: Jeff Carlach	
Phone: 303-756-6502	

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

## Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:					
	Items	in back.	yer d		
item:		<del> </del>			
item:					
item:				·····	
item:					
Item:	·				
item:	7				
Item:			· · · · · · · · · · · · · · · · · · ·		



· Project Resources Inc.

## Items To Be Removed By Contractor During Remediation And <u>Not Replaced</u> (Use additional sheets as necessary)

Item:	NIA
Item:	
Item:	
Item:	
Item:	
Item:	·
item:	



Project Resources Inc.

## Items To Be Removed By Contractor During Remediation And Replaced (Use additional sheets as necessary)

Item:	NIA
Item:	
Itém:	
item:	

## Landscape Inventory (Use additional sheets as necessary)

Item	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	2 <del>5/8</del> 2543	Square Feet	
Number of trees > 2 inch trunk diameter	N/A		
Number of trees < 2 inch trunk diameter	NJA		
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc.  Attach a sketch of the sprinkler layout.	MA		Zones:         \( \mathcal{V} \subseteq \mathcal{L} \)           Heads:         \( \mathcal{N} \subseteq \mathcal{L} \)           Control Valves:         \( \mathcal{N} \subseteq \mathcal{L} \)
Number of and total size of all gardens / flower beds.	# Of Beds:		Ft <sup>2</sup> Of Beds: N/A
Attach a sketch of relative sizes and locations.	# Of Gardens:		Ft <sup>2</sup> Of Gardens:

## Project Resources Inc.

Item	Quantity	Unit	Description/Explanation	
Agreed upon value of plant materials not to be replaced by contractor.  Store this value will be used to issue a plant votcher to the property owner.	Total # Of Beds:	\$	Total Ft <sup>2</sup> Of Beds To Be Replaced With Certifica	
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed.  Include a sketch of were each plant will be piaced by the contractor.	NJA	Each	Only Use For Plants That Are Being Saved and Replanted	
Agreed upon area of property to be replaced with grass sod.  Include a sketch of the area(s) to be replaced with grass sod.	3011	SF	Total Ft <sup>2</sup> Of Sod To Be Laid: 3 © 6	
Area of City or County property to be landscaped per their requirements.  Include a sketch of the area (s)	Total Ft <sup>2</sup> :	SF	Sod:	
Agreed upon area of property to be replaced with mulch.	Total Ft <sup>2</sup> Of Mulch:	SF	Red:         NF           Brown:         N/A	

颯
---

## Project Resources Inc.

ltem	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Fr <sup>2</sup> Of Rock:	SF	Large:
Agreed upon area to be replaced with no groundcover.	Total Ft <sup>2</sup> With No Groundcover: 378		

	Additional Comments / maductions.
	,
	·
	;
	-,
1	Done 6

#### **Additional Comments / Instructions Continued:**

would like to put in sprinkler system. (hold off on sod)

out of town March 28 - Apr. Co

owner wents a tendem load of medium in backyard do not spread

leave grade of soil 2" below sidewalk in fronty and where possible.

Be very exceful with flagstone owner very conserned

Check the box if Owner does not want PRI to document interior foundation walls and possible pre-existing damage. By checking this box PRI is not responsible for any damage done to the interior of house, including foundation cracks or fissures. ∐ I do not agree ∐ agree I do not agree 3-23-04 Contractor's Signature Date

Page 7




HalillionshiallillianMootillidalaaalMootilal





SEPA VB/I-70 Command Post 10 E. 55th Avenue Denver, CO 80216



### **TARGET SHEET**

## EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

VASQUEZ BOULEVARD AND I-70

DOCUMENT NOT SCANNED  Due to one of the following reasons:  PHOTOGRAPHS  3-DIMENSIONAL  OVERSIZED  AUDIO/VISUAL  PERMANENTLY BOUND DOCUMENTS	SI	ΓΕ NAME:	VASQUEZ BOULEVARD AND I-70
Due to one of the following reasons:  ☐ PHOTOGRAPHS ☐ 3-DIMENSIONAL ☐ OVERSIZED ☐ AUDIO/VISUAL ☐ PERMANENTLY BOUND DOCUMENTS	DC	CUMENT DATE:	05/29/2004
<ul> <li>□ PHOTOGRAPHS</li> <li>☑ 3-DIMENSIONAL</li> <li>□ OVERSIZED</li> <li>□ AUDIO/VISUAL</li> <li>□ PERMANENTLY BOUND DOCUMENTS</li> </ul>			DOCUMENT NOT SCANNED
<ul> <li>☑ 3-DIMENSIONAL</li> <li>☐ OVERSIZED</li> <li>☐ AUDIO/VISUAL</li> <li>☐ PERMANENTLY BOUND DOCUMENTS</li> </ul>	Du	e to one of the fol	lowing reasons:
□ OVERSIZED □ AUDIO/VISUAL □ PERMANENTLY BOUND DOCUMENTS		PHOTOGRAPHS	
☐ AUDIO/VISUAL ☐ PERMANENTLY BOUND DOCUMENTS	V	3-DIMENSIONAL	
□ PERMANENTLY BOUND DOCUMENTS		OVERSIZED	
		AUDIO/VISUAL	
		PERMANENTLY I	BOUND DOCUMENTS
□ POOR LEGIBILITY		POOR LEGIBILIT	Y
□ OTHER		OTHER	
□ NOT AVAILABLE		NOT AVAILABLE	
☐ TYPES OF DOCUMENTS NOT TO BE SCANNED (Data Packages, Data Validation, Sampling Data, CBI, Chain of Custody			
DOCUMENT DESCRIPTION:	DC	CUMENT DESCR	IPTION:
PROPERTY #2305 SAMPLE: BROWN PORCH TRIM, EAST, WOOD		PROPERTY #230	5 SAMPLE: BROWN PORCH TRIM, EAST, WOOD
		<del></del>	

### **TARGET SHEET**

## EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1051761

SI	TE NAME: VASQUEZ BOULEVARD AND I-70
D	OCUMENT DATE: 05/29/2004
Di	DOCUMENT NOT SCANNED ue to one of the following reasons:
	PHOTOGRAPHS
	3-DIMENSIONAL
	OVERSIZED
Ø	AUDIO/VISUAL
	PERMANENTLY BOUND DOCUMENTS
	POOR LEGIBILITY
	OTHER
	NOT AVAILABLE
	TYPES OF DOCUMENTS NOT TO BE SCANNED (Data Packages, Data Validation, Sampling Data, CBI, Chain of Custody)
DO	DOCUMENT DESCRIPTION:
	3 - DVDs OF PROPERTY VIDEO, PROPERTY #2305